

## **FIRST, CLEAN THE SURFACES TO BE JOINED!**

Are you going to use an adhesive? Cleaning and degreasing the surfaces to be bonded is essential and certainly not difficult.

If you are going to bond, to ensure a reliable adhesion you must first clean the surfaces to be connected well. The quality and durability of the adhesion deteriorates if the adhesive cannot be properly applied to the surfaces due to dust or grease.

It is necessary to remove residual dirt, grease, oil, fingerprints and dust from the parts to be bonded.

Of course, it is important to use a product that dissolves contaminations without affecting or damaging the substrates. Therefore, only use a degreasing agent produced by the adhesive supplier: TWEHA Cleaner+. This is precisely tuned to the specific adhesive process.

One thing is certain: never use thinner, benzene, petrol or brake cleaner to degrease surfaces to be bonded.