



ALL ABOUT CLEANING SURFACES BEFORE BONDING

Are you going to us an adhesive? Cleaning and degreasing the surfaces to be bonded is essential and certainly not difficult.

If you are going to bond, to ensure a reliable adhesion you must first clean the surfaces to be connected well. The quality and durability of the adhesion deteriorates if the adhesive cannot be properly applied to the surfaces due to dust or grease.

It is necessary to remove residual dirt, grease, oil, fingerprints and dust from the parts to be bonded. For this purpose, a degreasing agent TWEHA Cleaner+ is used.

Of course, it is important to use a product that dissolves contamination without affecting or damaging the substrates. Therefore, only use a degreasing agent produced by the adhesive supplier. These are precisely tuned to the specific adhesive process.

One thing is certain: never use thinner, benzene, petrol or brake cleaner to de-grease surfaces to be bonded.

TWEHA 2022